10 February 1965

Dear Russ:

Enclosed are two (2) copies each of installation Drawing No. 1-120-E-661 and 1-120-E-1449; data on the imposed heat loads and data on air discharged from the dryers of each of the processing machines being built on PAR 214 and PAR 215.

This is information we agreed to furnish during our 17 December 1964 visit to your facility.

In addition to the information tabulated, asked if a disconnect is required ahead of the main circuit breakers on each of the machines. The circuit breakers supplied with the machines will be sized to handle the total connected load. Consequently, disconnects would serve no purpose other than to isolate the main breakers. Since this could probably be handled in your service panel, we believe that the disconnects are not required.

Please let us know if you have any further questions regarding the installation of the machines.

Rock

BEST RELARDS,

one copy of each of 25X1 the above farmanded to

Declass Review by NGA.

Approved For Release 2005/02/17: CIA-RDP78B04770A001000040089-1

25X1